March 6, 2018

Clemson University
310 Klugh Avenue
Clemson, South Carolina 29634

Attn: Mr. W. Robert Newberry, IV
E-mail: wnewber@clemson.edu

Re: Limited Mold and Allergen Investigation Report
Manning Hall Student Housing, Unit 8D4
Clemson, South Carolina 29631
Terracon Project No. 86127158 – Task 127

Dear Mr. Newberry:

Terracon Consultants, Inc. (Terracon) conducted a limited mold and allergen investigation in Unit 8D4 of Manning Hall at Clemson University in Clemson, South Carolina. Reportedly, residents of this dormitory room have reported respiratory irritation. This service was conducted in general accordance with our Master Service Agreement with Clemson University.

PROJECT DESCRIPTION

Scope of Services

At the request of Clemson University, Terracon representative Mr. Stephen Ellis conducted a limited mold and allergen investigation in Unit 8D4 at Manning Hall, on Thursday, February 8, 2018. Manning Hall was constructed in 1967. This student housing unit contains 2 bunk beds, 2 sets of drawers and 2 closets. This dorm unit is located on the 8th floor.

On our February 8th visit, Terracon made measurements of temperature and relative humidity and conducted airborne mold sampling which consisted of collecting spore trap air samples in one location inside the dorm and the collection of two additional samples outside for comparison. We also collected a composite dust samples for allergen analysis.

Standard of Care

This limited mold and allergen investigation was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions in the same locale. Terracon did not attempt to identify every potential exposure or hazard present in the subject building. The results, findings, conclusions and recommendations expressed in this report are based on conditions observed during our sampling. Many factors, such as weather conditions, building occupancy, ventilation patterns and seasonal variations in fungal concentrations, can affect the conditions observed. The information contained in this report should not be relied upon to represent conditions that existed prior to or after this sampling. Terracon does not warrant the services of regulatory agencies, laboratories or other third parties supplying information that may have been used in the preparation of this report.

SAMPLING CRITERIA AND METHODS

Mold and Allergen Sampling

Total mold spore trap samples were collected using Allergenco-D™ spore trap cassettes specifically designed for the collection of airborne mold spores. Air samples were collected using a calibrated Zefon Bio-Pump™ at a flow rate of 15 liters per minute (LPM) for 5 minutes at each location.

After collection, the spore trap samples were hand delivered to the Southeastern Environmental Microbiology Lab (SEEML) in Greenville, South Carolina. SEEML is accredited by the AIHA® Laboratory Accreditation Programs, LLC under the Environmental Microbiology Laboratory Accreditation Program (EMLAP), Accreditation #173667. Air samples were analyzed by direct microscopic examination and results are reported in spores per cubic meter of air (spores/m^3).

To help interpret the mold sampling results, we compared indoor air and outdoor air measurements. High variability in airborne fungal spore concentrations can exist in different geographic locations, during different seasons, and weather patterns, and over the course of a given day. As a general rule, indoor air fungal spore concentrations in a heating, ventilation and air-conditioning (HVAC)-supplied building are typically less than, but qualitatively similar to, fungal spore concentrations found in the outside environment.

No state or federal exposure limits have been established for fungal aerosols. Regulatory standards, medically based threshold limit or dose-response relationships have not been established for exposure to airborne or surface concentrations of mold spores. Terracon relies upon experience, professional judgment, current scientific literature, guidelines and recommendations made by professional organizations and experts, and statistical methods in interpreting mold sampling results.

A composite allergen dust sample was collected from carpet, chair fabrics and furniture surfaces in the dorm room using a high volume air sampling pump in conjunction with a 3-piece 37 millimeter dust sampling cassette preloaded with a 5.0 micrometer polyvinyl chloride (PVC) filter.

After composite dust sample collection, the allergen sample was shipped by overnight courier to EMSL in Cinnaminson, New Jersey. EMSL is accredited by the AIHA® Laboratory Accreditation Programs, LLC under the Environmental Microbiology Laboratory Accreditation Program (EMLAP), Accreditation #100194. The allergen sample was analyzed by direct microscopic examination for allergens from dust mites, mouse, rat, cat, dog, and cockroach. Allergen results are reported in micrograms per gram of dust (µg/g).

Temperature and Relative Humidity

Indoor air temperature and relative humidity are physical conditions important to the perception of comfort. The American Society of Heating, Refrigerating, and Air-Conditioning Engineers (ASHRAE) has published recommendations regarding thermal comfort. ASHRAE Standard 55-2013, Thermal Environmental Conditions for Human Occupancy, identifies six primary factors that affect comfort: metabolic rate (affected by the activity being performed); clothing insulation; air temperature; radiant temperature; air speed; and humidity.

Although the relationships are complex, a temperature range between 73 and 79 degrees Fahrenheit (°F) with relative humidity between roughly 20 and 60 percent (%) are recommended for persons in a conditioned setting wearing light summer clothing. Higher temperatures require lower humidity for comfort. For persons in winter clothing, temperatures can range between 68 and 75°F, with relative humidity between 20% and 60%, with preferred conditions falling between 30% and 50% for both winter and summer temperatures.

EPA recommends maintaining indoor humidity below 60%, ideally 30-50%, if possible.

Readings of temperature and relative humidity were collected with an Extech Model 445580 IAQ instrument which was calibrated by the manufacturer.

FINDINGS

General Observations

- No evidence of mold growth was observed.
- Damage to an outer wall behind one of the elevated bedframes was observed and appeared to be water-related.
- Water infiltration was also observed beneath carpet square flooring.
- Photographs from the assessment are attached.

Mold Air Sampling

On the afternoon of February 8, 2018, Terracon collected a mold spore trap sample inside the dorm at 8D4 Manning Hall and two samples in outdoor locations for comparison. The results of the total spore count samples analyses are summarized in Table 1 below:

Table 1: Summary of Total Spore Count Analyses – February 8, 2018

Sample #	AS-1	EX-1	EX-2	BL
Location Description	**Room 8D4**	**Exterior 1**	**Exterior 2**	**Blank**
Spore Type	**Spores/m^3**	**Spores/m^3**	**Spores/m^3**	**Spores/m^3**
Alternaria	---	---	13	---
Ascospores	39	195	312	
Basidiospores	390	1,990	2,910	---
Bipolaris/Dreschlera	13			
Cladosporium	117	663	741	---
Epicoccum	117	---	---	---
Penicillium/ Aspergillus	273	156	234	---
Smuts/*Periconia*/ Myxomycetes	169	13	---	---
Total	**1,120**	**3,020**	**4,210**	**ND**
Temperature (degrees F.)	71.6	62.4	---	---
Relative Humidity (%)	27.8	22.1	---	---

There was no visual evidence of mold growth in the dorm room. Wet building materials were observed on the outer wall of the room.

The highest outdoor total spore count was approximately 3.75 times higher than the highest total spore count inside. The predominant mold genera indoors was *Basidiospores.* The predominant mold spore types outdoors were *Cladosporium and Basidiospores*. The weather on the day we sampled was moderate (62ºF) with a slight breeze. The laboratory analytical report is attached.

Temperature and Relative Humidity

The indoor temperature was 71ºF and the relative humidity was 27%. The outdoor temperature was 62ºF and the relative humidity was 22%.

Allergen Sampling

On the afternoon of February 8, 2018, Terracon collected a dust sample from the carpeting, chair fabric, and furniture in the dorm room at 8D4 Manning Hall. The samples were analyzed for allergens from dust mites, mouse, rat, cat, dog, and cockroach.

Allergens were identified in the samples. Table 2 below summarizes the laboratory results. The laboratory analytical report is attached and references additional information.

Table 2: Summary of Allergen Analyses – February 8, 2018

Sample #	DS-1	
Location Description	**Composite from floor near closet**	
Allergen Type/Antigen	**Concentration (ug/g)**	**Laboratory assigned risk factor**
Dust Mites / Der fl	ND	NA
Dust Mites / Der pl	ND	NA
Mouse / Mus ml	ND	NA
Rat / Rat nl	ND	NA
Cat / Fel dl	0.13	Low
Dog / Can fl	22.63	High
Cockroach / Bla G2	ND	NA

Note: ug = microgram (10^{-6} grams), NA = Not Applicable, ND = not detected

CONCLUSIONS

The following conclusions are provided based on our assessment:

- The results of mold air sampling indicated that total airborne mold spore concentrations inside the building were below the total mold spore levels measured in the highest outdoor sample. Additionally, the predominant mold spore indoors was also observed in the outdoor samples. This may be considered favorable.

- Other than dog allergens, low or non-detectable levels of common allergens were identified from the dust samples collected in the room and the allergen risk level assigned by the lab was low.

- The “High” risk factor for dog allergens should be reported to the residents in the event they have an allergy to dog dander.

- There was no visual evidence of mold growth in the dorm room at this time. This space should be monitored periodically until the exterior repairs are corrected. In the interim carpeting and the wall should be dried to prevent microbial growth.

- Reportedly, repairs to the curtain wall are scheduled to address water infiltration through the walls during rain events with high winds causing a "driving" rain.

- Temperature and relative humidity levels were within ASHRAE and EPA guideline ranges, respectively.

Terracon appreciates the opportunity to provide this service to Clemson University. If you have any questions regarding this limited mold and allergen investigation report, please contact the undersigned at 864-292-2901.

Sincerely,
Terracon Consultants, Inc.

Benjamin Hestir, P.E.
Project Industrial Hygienist

Jeffrey A. Gurrie
Senior Industrial Hygienist

Attachments: Photographs
Laboratory Results

Photographs




Photo #1 View of water damage on exterior wall in Room 8D4



Photo #2 View of water seepage under carpet squares in Room 8D4



Photo #3 Closer view of exterior wall in Room 8D4

Laboratory Results

SEEML Reference Number:
180209009

Southeast Environmental Microbiology Laboratories
102 Edinburgh Court
Greenville, SC 29607
Phone: (864) 233-3770
FAX: (864) 233-6589

The information and data for **Terracon** has been checked for thoroughness and accuracy. The following reports are contained within this document:

- ☐ Surface/Bulk Report
- ☒ Spore Trap Report
- ☐ Andersen Fungal Report
- ☐ Quantitative Fungal Report

Lab Manager Review: Rafael Berrios Date: 02/09/18

Thank you for using SEEML laboratories. We strive to provide superior quality and service.
SEEML laboratories are accredited through AIHA-LAP, LLC (EMLAP # 173667) for the analysis of Spore Traps and Surface/Bulk Samples.

The data within this report is reliable to three significant figures. The third significant figure is technically unjustified. In this instance, the third figure is reported as an estimate to facilitate the interpretation by the customer.

Confidentiality Notice:
The document(s) contained herein are confidential and privileged information, intended for the exclusive use of the individual or entity named above. If the reader of this message is not the intended recipient, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that any dissemination, distribution or copying of the document(s) is strictly prohibited. If you have received this document in error, please immediately notify us by telephone to arrange for its return. Thank you.

Guidelines for Interpretation:
No accepted quantitative regulatory standards currently exist by which to assess the health risks related to mold and bacterial exposure. Molds and bacteria have been associated with a variety of health effects and sensitivity varies from person to person.
Several organizations, including: the American Conference of Government Industrial Hygienists (ACGIH); the American Industrial Hygiene Association (AIHA); the Indoor Air Quality Association (IAQA); the United States Environmental Protection Agency (USEPA); the Centers for Disease Control (CDC), as well as the California Department of Health Services (CADHS), have all published guidelines for assessment and interpretation of mold resulting from water intrusion in buildings.

Interpretation of the data and information within this document is left to the company, consultant, and/or persons who conducted the fieldwork.

Spore Trap Report

	Date Sampled: 02/08/18
Terracon	Date Received: 02/09/18
72 Pointe Circle	Date Analyzed: 02/09/18
Greenville, SC 29615	Date Reported: 02/09/18
	Date Revised:
	Project Name: 86127152 Task 127
	Project Address: Manning Hall
	Project City, State, ZIP: Clemson, SC.
	SEEML Reference # : 180209009

TEST METHOD: DIRECT MICROSCOPY EXAMINATION AT 400X (100% OF TRACE ANALYZED) SEEML SOP 7

Client Sample ID	AS-1			EX-1			EX-2		
Location	Room 8D4			Exterior 1			Exterior 2		
Lab Sample ID	180209009-049			180209009-050			180209009-051		
Detection Limit (spores/m^3)	13			13			13		
Hyphal Fragments	8	104					1	13	
Pollen							1	13	
Spore Trap Used	AOC			AOC			AOC		
	raw ct.	spores/m^3	%	raw ct.	spores/m^3	%	raw ct.	spores/m^3	%
Alternaria							1	13	<1
Ascospores	3	39	3	15	195	6	24	312	7
Basidiospores	30	390	35	153	1990	66	224	2910	69
Bipolaris/Drechslera	1	13	1						
Chaetomium									
Cladosporium	9	117	10	51	663	22	57	741	18
Curvularia									
Epicoccum	9	117	10						
Cercospora									
Fusarium									
Memnoniella									
Nigrospora									
Penicillium/Aspergillus	21	273	24	12	156	5	18	234	6
Polythrincium									
Rusts									
Smuts/Periconia/Myxomy	13	169	15	1	13	<1			
Spegazzinia									
Stachybotrys									
Stemphylium									
Tetraploa									
Torula									
Ulocladium									
Colorless/Other Brown 2									
Oidium									
Zygomycetes									
Pithomyces									
Background debris (1-5)3	3			2			2		
Sample Volume(liters)	75			75			75		
TOTAL SPORES/M^3	86	**1120**		232	**3020**		324	**4210**	

Comments: Condition of the sample(s) upon receipt: Acceptable.

1=Total % may not equal 100 due to rounding.

2 = Colorless,other Brown are spores without a distinctive morphology on spore traps and non-viable surface samples.

3 = Background debris is the amount of particulate matter present on the slide and is graded from 1-5 with 1 = very light, 2= Light, 3 = Medium, 4 = Heavy, 5 = Very Heavy. The higher the rating the more likelihood spores may be underestimated. A rating of 5 should be interpreted as minimal counts and may actually be higher than reported.

The reporting limit is 1 Spore/sample.

Disclaimer: This report relates only to the samples tested

Respectfully submitted, SEEML

Rafael Berrios

Rafael Berrios, Approved Laboratory Signatory

102 Edinburgh Court
Greenville, SC 29607
Phone: (864) 233- 3770
Fax: (864) 233-6589
AIHA-LAP, LLC EMLAP # 173667

Spore Trap Report

	Date Sampled: 02/08/18
Terracon	Date Received: 02/09/18
72 Pointe Circle	Date Analyzed: 02/09/18
Greenville, SC 29615	Date Reported: 02/09/18
	Date Revised:
	Project Name: 86127152 Task 127
	Project Address: Manning Hall
	Project City, State, ZIP: Clemson, SC.
	SEEML Reference # : 180209009

TEST METHOD: DIRECT MICROSCOPY EXAMINATION AT 400X (100% OF TRACE ANALYZED) SEEML SOP 7

Client Sample ID	BL								
Location	Blank								
Lab Sample ID	180209009-052								
Detection Limit (spores/m^3)									
Hyphal Fragments									
Pollen									
Spore Trap Used	AOC								
	raw ct.	spores/m^3	%						
Alternaria									
Ascospores									
Basidiospores									
Bipolaris/Drechslera									
Chaetomium									
Cladosporium	No								
Curvularia	Trace								
Epicoccum									
Cercospora									
Fusarium									
Memnoniella									
Nigrospora									
Penicillium/Aspergillus									
Polythrincium									
Rusts									
Smuts/Periconia/Myxomy									
Spegazzinia									
Stachybotrys									
Stemphylium									
Tetraploa									
Torula									
Ulocladium									
Colorless/Other Brown 2									
Oidium									
Zygomycetes									
Pithomyces									
Background debris (1-5)3									
Sample Volume(liters)									
TOTAL SPORES/M^3		**#VALUE!**							

Comments: Condition of the sample(s) upon receipt: Acceptable.

1=Total % may not equal 100 due to rounding.

2 = Colorless,other Brown are spores without a distinctive morphology on spore traps and non-viable surface samples.

3 = Background debris is the amount of particulate matter present on the slide and is graded from 1-5 with 1 = very light, 2= Light, 3 = Medium, 4 = Heavy, 5 = Very Heavy. The higher the rating the more likelihood spores may be underestimated. A rating of 5 should be interpreted as minimal counts and may actually be higher than reported.

The reporting limit is 1 Spore/sample.

Disclaimer: This report relates only to the samples tested

Respectfully submitted, SEEML

Rafael Berrios

Rafael Berrios, Approved Laboratory Signatory

102 Edinburgh Court
Greenville, SC 29607
Phone: (864) 233- 3770
Fax: (864) 233-6589
AIHA-LAP, LLC EMLAP # 173667

Southeast Environmental Microbiology Laboratories
Chain of Custody

SEEML Labs
Analytical Solutions For a Healthy Indoor Environment
102 Edinburgh Court, Greenville, SC 29607
Phone : 864-233-3770, Fax: 864-233-6589, www.seeml.com, AIHA-LAP, LLC. (EMLAP) #173667

For Lab Use Only

Condition of samples is acceptable	☑ YES ☐ NO	SEEML Ref #: 1802090009	Lab ID: 049- 052

Company Information		Client Information		Environmental Conditions	
(Project Manager)	Ben Hestir	Date Sampled:	2-8-18	Precipitation in last 16hrs:	No
(Company Name)	Terracon	Project Name:	86127152 Task 127	Relative Humidity I/O:	27.8 / 22.1
(Address)	72 Pointe Circle	Project Address:	Manning Hall	Temperature I/O:	71.6 / 62.4
(City, State, Zip)	Greenville, SC 29615	City, State, Zip:	Clemson, SC	Wind Conditions	Light
(Phone)	864-292-2901				
(Email)	Ben.Hestir@terracon.com				

Sample Type Abbreviations:
A- Allergenco **S**-Swab **AP**-Andersen Plate
AOC- Air O Cell **T**-Tape **W**- Water
M5- Micro 5 **B**- Bulk **D**- Dust

Analysis Type:
1. SporeTrap, Air Sample Analysis-Same Day
2. Direct Exam Surface Sample Analysis -Same Day
3. Culturable Air / Surface Samples -7-10 days

Sample ID	Sample Location	Sample Type	Analysis Type	*Area	**Volume (L)	Notes
AS-1	Room 8D4	A	1		75L	
EX-1	Exterior 1	A	1		75L	
EX-2	Exterior 2	A	1		075L	
BL	Blank	A	1		0L	

Reliquished By:	Date/Time	Recieved By:	Date/Time
	2-8-18 1650		2-9-18

*Area is only required for culturable surface samples.
**Volume = Pump setting (L/min) x minutes

EMSL Analytical, Inc.
200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800)220-3675 / (856)786-0262
http://www.EMSL.com cinnmicrolab@emsl.com

EMSL Order #:	**371802456**
Customer ID:	**GTER78**
Customer PO:	**86127158-127**

Attn: **Ben Hestir**
Terracon Consultants, Inc.
72 Pointe Circle
Greenville, SC 29615

Phone: **864-292-2901**
Fax: **864-292-6361**

Project: **Manning 8D4**

Date Collected: **Not Provided**
Date Received: **2/12/2018**
Date Analyzed: **2/15/2018**

Sample Summary -Indoor Allergen Analysis by MARIA®



Lab Sample Number	Client Sample ID	Sample Location	Sample Type
371802456-0001	DS-1	Near Closet Room	Bulk

Report Date	Report Revision	Revision Comments
2/19/2018	R0	Initial Report

Vincent Iuzzolino, M.S., Laboratory Director
or approved EMSL Analytical, Inc. signatory

About Us

EMSL Analytical, Inc. offers a full line of analytical solutions for over 30 years across North America. For more information about our nationally accredited locations, vast line of testing services, and our food safety solutions please visit www.EMSL.com or call



Disclaimers

All samples were collected by and all sampling data was provided by the client. The results are valid only for those samples analyzed, and only for those samples collected in accordance with the appropriate methodology as determined by the client. The results herein do not denote or represent a medical or clinical diagnosis or conclusion. In the event that sample(s) were submitted in opened, used, non-sterile or otherwise adulterated condition, EMSL shall not be responsible or liable. EMSL Analytical (Cinnaminson, NJ) is accredited by the American Industrial Hygiene Association (AIHA) in the EMLAP accreditation program for specified Field(s) of Testing as documented on the scope of accreditation.

Please visit our website at http://www.microbiologytestinglab.com/
© 2016, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.

EMSL Analytical, Inc.
200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800)220-3675 / (856)786-0262
http://www.EMSL.com cinnmicrolab@emsl.com

EMSL Order #: **371802456**
Customer ID: **GTER78**
Customer PO: **86127158-127**

Attn: **Ben Hestir**
Terracon Consultants, Inc.
72 Pointe Circle
Greenville, SC 29615

Phone: **864-292-2901**
Fax: **864-292-6361**

Project: **Manning 8D4**

Date Collected: **Not Provided**
Date Received: **2/12/2018**
Date Analyzed: **2/15/2018**

EMSL Sample #: **371802456-0001**
Client ID: **DS-1**
Location: **Near Closet Room**

Sample Type: **Bulk**
Sample Size: **62**
Sample Units: **mg**

Analytical Results -Indoor Allergen Analysis by MARIA®

Test Parameter	*Antigens*	*Detection Limits*		*Concentrations*		*Allergen Risk Levels*
Dust Mites Allergen	Der f1	0.012	µg/g	**ND**	µg/g	☑
Dust Mites Allergen	Der p1	0.012	µg/g	**ND**	µg/g	☑
Mouse Allergen	Mus m1	0.002	µg/g	**ND**	µg/g	☑
Rat Allergen	Rat n1	0.004	µg/g	**ND**	µg/g	†
Cat Allergen	Fel d1	0.004	µg/g	**0.13**	µg/g	☑
Dog Allergen	Can f1	0.012	µg/g	**22.63**	µg/g	⊘
Cockroach Allergen	Bla g2	0.024	µg/g	**ND**	µg/g	☑

†Sufficient evidence is not available for risk levels.

Allergen Risk Levels:

⊘ **High** -Risk of acute asthmatic attack.

⚠ **Moderate** -Risk for sensitization and bronchial hyperactivity.

☑ **Low** -Not sufficient to cause symptoms or ND (None Detected); Indicates that the amount of allergen in the sample is below the detection limits.

All samples were collected by and all sampling data was provided by the client. The results are valid only for those samples analyzed, and only for those samples collected in accordance with the appropriate methodology as determined by the client. The results herein do not denote or represent a medical or clinical diagnosis or conclusion. In the event that sample(s) were submitted in opened, used, non-sterile or otherwise adulterated condition, EMSL shall not be responsible or liable.

EMSL Analytical (Cinnaminson, NJ) is accredited by the American Industrial Hygiene Association (AIHA) in the EMLAP accreditation program for specified Field(s) of Testing as documented on the scope of accreditation.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report

Report Date	**Report Revision**	**Revision Comments**
2/19/2018	R0	Initial Report

Vincent Iuzzolino, M.S., Laboratory Director
or approved EMSL Analytical, Inc. signatory

Please visit our website at http://www.microbiologytestinglab.com/
© 2016, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.

EMSL Analytical, Inc.
200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800)220-3675 / (856)786-0262
http://www.EMSL.com cinnmicrolab@emsl.com

EMSL Order #: **371802456**
Customer ID: **GTER78**
Customer PO: **86127158-127**

Attn: **Ben Hestir**
Terracon Consultants, Inc.
72 Pointe Circle
Greenville, SC 29615

Phone: **864-292-2901**
Fax: **864-292-6361**

Project: **Manning 8D4**

Date Collected: **Not Provided**
Date Received: **2/12/2018**
Date Analyzed: **2/15/2018**

Guidelines to Interpretation

µg/g

Allergens	<DL	<1	1	2	3	4	5	6	7	8	9	>10
Fel d1	ND	Low	Mod	Mod	Mod	Mod	Mod	Mod	Mod	High	High	High
Can f1	ND	Low	Low	Mod	Mod	Mod	Mod	Mod	Mod	Mod	Mod	High
Der p1	ND	Low	Low	Mod	Mod	Mod	Mod	Mod	Mod	Mod	Mod	High
Der f1	ND	Low	Low	Mod	Mod	Mod	Mod	Mod	Mod	Mod	Mod	High
Mus m1	ND	Low	Mod	Mod	Mod	High	High	High	High	High	High	High

µg/m3

Rat n1	ND	<0.7 µg /m3 = Not associated with increased risk of asthma

µg/g

	<DL	<0.08	0.08	0.09	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8
Bla g2 †	ND	Low	Mod	Mod	Mod	Mod	Mod	Mod	High	High	High	High

† *Suggested levels. Not officially established.*

Note: *This report and guidelines furnish information only. Whether an individual suffers allergic symptoms or not depends on his/her medical history and previous exposure.*

References

Journal of Allergy and Clinical Immunology 1989; 83:416-427
Journal of Allergy and Clinical Immunology 1995; 96:449-456
The American review of respiratory disease 1990; 141:361-367
The American review of respiratory disease 1993; 147:573-578
Environmental Health Perspectives 2002; 110:419-425
Clinical and Experimental Allergy 1998; 28(5):537-44
Pediatric allergy-principles and practice. Mosby Inc 2003: 261-268.

Terminology

ELISA	Enzyme-linked Immunosorbent Assay
MARIA®	Multiplex Array for Indoor Allergens
Allergen	A substance which reacts with the body's immune system to produce an allergic reaction.
Antigen	A substance, foreign to the body, which stimulates the production of antibodies by the immune system.
Bla g2	*Blattella germanica* (Cockroach) allergen 2
Can f1	*Canis familiaris* (Dog) allergen 1
Der f1	*Dermatophagoides farinae* (Dust Mites) allergen 1
Der p1	*Dermatophagoides pteronyssinus* (Dust Mites) allergen 1
Detection Limits	DL is the smallest amount of a substance, in this case antigens, which can be measured.
Fel d1	*Felis domesticus* (Cat) allergen 1
Mus m1	*Mus musculus* (Mouse) allergen 1
ND	None detected, if any allergens are present they are below the detection limits.
Rat n1	*Rattus norvegicus* (Rat) allergen 1

Please visit our website at http://www.microbiologytestinglab.com/
© 2016, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.

EMSL Analytical, Inc.
200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800)220-3675 / (856)786-0262
http://www.EMSL.com cinnmicrolab@emsl.com

EMSL Order #: **371802456**
Customer ID: **GTER78**
Customer PO: **86127158-127**

Attn: **Ben Hestir**
Terracon Consultants, Inc.
72 Pointe Circle
Greenville, SC 29615

Phone: **864-292-2901**
Fax: **864-292-6361**

Project: **Manning 8D4**

Date Collected: **Not Provided**
Date Received: **2/12/2018**
Date Analyzed: **2/15/2018**



Important Terms, Conditions, and Limitations

A. Sample Retention
Samples analyzed by EMSL will be retained for 60 days after analysis date. Storage beyond this period is available for a fee with written request prior to the initial 30 day period. Samples containing hazardous/toxic substances which require special handling will be returned to the client immediately. EMSL reserves the right to charge a sample disposal fee or return samples to the client.

B. Change Orders and Cancellation
All changes in the scope of work or turnaround time requested by the client after sample acceptance must be made in writing and confirmed in writing by EMSL. If requested changes result in a change in cost the client must accept payment responsibility. In the event work is cancelled by a client, EMSL will complete work in progress and invoice for work completed to the point of cancellation notice. EMSL is not responsible for holding times that are exceeded due to such changes.

C. Warranty
EMSL warrants to its clients that all services provided hereunder shall be performed in accordance with established and recognized analytical testing procedures and with reasonable care in accordance with applicable federal, state and local laws. The foregoing express warranty is exclusive and is given in lieu of all other warranties, expressed or implied. EMSL disclaims any other warranties, express or implied, including a warranty of fitness for particular purpose and warranty of merchantability.

D. Limits of Liability
In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. EMSL will not be held responsible for the improper selection of sampling devices even if we supply the device to the user. The user of the sampling device has the sole responsibility to select the proper sampler and sampling conditions to insure that a valid sample is taken for analysis. Any resampling performed will be at the sole discretion of EMSL, the cost of which shall be limited to the reasonable the original sample delivery group (SDG) samples. In no event shall EMSL be liable to a client orvalue of any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder.

E. Indemnification
Client shall indemnify EMSL and its officers, directors and employees and hold each of them harmless for any liability, expense or cost, including reasonable attorney's fees, incurred by reason of any third party claim in connection with EMSL's services, the test result data or its use by client.

This report has been prepared by EMSL Analytical, Inc. at the request of and for the exclusive use of the client named in this report. Completely read the important terms, conditions, and limitations that apply to this report.

Report Date	Report Revision	Revision Comments
2/19/2018	R0	Initial Report

Vincent Iuzzolino, M.S., Laboratory Director
or approved EMSL Analytical, Inc. signatory

Please visit our website at http://www.microbiologytestinglab.com/
© 2016, EMSL Analytical, Inc., All rights reserved. No part of this report may be reproduced or otherwise distributed or used without the express written consent of EMSL.

EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Industrial Hygiene Chain of Custody

EMSL Order Number (Lab Use Only): 371802456

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: (800) 220-3675
FAX: (856) 858-3502

Report To Contact Name: Ben Hestir		Bill To Company: Terracon GTER78	Client ID #:
Company Name: Terracon Consultants		Attention To:	
Street: 72 Pointe Circle		Street:	
City: Greenville	State/Province: SC	Zip/Postal Code: 29615	City:	State/Province:	Zip/Postal Code:
Phone: 864-293-7348	Fax:	Phone:	Fax:
Project Name: Manning 804		Email Results To: Ben.Hestir@terracon.com	U.S. State where Samples Collected: SC
# Samples in Shipment: 1	Date of Shipment: 2-8-18	Purchase Order: 86127158-12[illegible]	Sampled By (Signature):

Turnaround Time (TAT) – Please Check: If No Selection Made, Standard 2 Week TAT Will Apply

☐ 2 Week ☑ 1 Week ☐ 4 Day ☐ 3 Day ☐ 2 Day ☐ 1 Day ☐ Other (Call Lab)

Media Type:

Manufacturer/Part #: Lot #:

RECEIVED EMSL CINNAMINSON, N.J. 2018 FEB 12 A 10: 28

Client Sample ID	Location/Description	Analyte / Method	Media	Flow (lpm)	Sample Time On	Sample Time Off	Volume / Area	Sample Type	Sample Date	Comments
DS-1	Near Closet Door	M038, M039 M044	Cassette	N/A			576 in²	☑ Area ☐ Personal	2-8-18	
								☐ Area ☐ Personal		
								☐ Area ☐ Personal		
								☐ Area ☐ Personal		
								☐ Area ☐ Personal		
								☐ Area ☐ Personal		
								☐ Area ☐ Personal		
								☐ Area ☐ Personal		

Note: Most NIOSH and OSHA methods require field blanks. It is the IH field sampler's responsibility to submit the proper number of field blanks and duplicates.

Released By	Date	Received By	Date
[signature]	2-8-18	[illegible]	2/12/18 1035

Comments:

(1)

OrderID: 371802456