

# Common Lab Inspection Findings

## Training

- PIs and Lab Personnel must complete all training required by Occupational and Environmental Safety.

## Labeling

- All chemical containers and storage areas must be properly labeled.

## Check Safety Equipment

- The Safety Shower must be tested monthly, and the Eyewash weekly.
- Fire Extinguisher visual inspections must be done monthly.

## Chemical Segregation

- Properly segregate incompatible chemicals. A storage guide can be found on the OES website.



<http://www.clemson.edu/finops/oes>

## Remember

Update Lab Door Signs

---

Contact OES before use of respirators/ dust masks

---